# **SY10-110 Technical Data Sheet**

On/Off Floating Point, Non-Spring Return, 110 V







Technical Data	
Power Supply	120 VAC, ±10%, 50/60 Hz
Transformer sizing	384 VA
Current consumption	3.2 A
Electrical Connection	Terminal blocks
Overload Protection	thermally protected 135°C cut-out
Angle of rotation	90°
Torque motor	22130 in-lb [2500 Nm]
Duty cycle	30%
Direction of motion motor	selectable with switch 0/1
Position indication	top mounted domed indicator
Manual override	hand wheel
Running Time (Motor)	62 s
Internal Humidty Control	resistive heating element
Ambient humidity	max. 95% r.H., non-condensing
Ambient temperature	-22150°F [-3065°C]
Storage temperature	-40176°F [-4080°C]
Degree of Protection	IP66/67, NEMA 4X, UL Enclosure Type 4X
Housing material	die cast aluminium
Gear train	high alloy steel gear sets, self locking
Agency Listing	ISO, CE, cCSAus
Noise level, motor	45 dB(A)
Servicing	maintenance-free
Quality Standard	ISO 9001
Weight	160 lb [73 kg]
Auxiliary switch	2 x SPDT, 3 A resistive (0.5 A inductive) @ AC 250
	V, one set at 10°, one set at 85°

#### **Application**

SY Series actuators are fractional horsepower devices, and utilize full-wave power supplies. Observe wire sizing and transformer sizing requirements. Proportional models CANNOT be connected to Belimo direct coupled (AF, AM, GM...etc) actuator power supplies or any type of half-wave device. You MUST use a separate, dedicated transformer or power supply to power the SY actuator. Please do not connect other automation equipment to the dedicated SY supply source. You MUST use four wires (plus a ground) to control a proportional control SY actuator (See SY Wiring Section).



## SY10-110 Technical Data Sheet

On/Off Floating Point, Non-Spring Return, 110 V

#### Wiring Diagrams



## X INSTALLATION NOTES



Do not change sensitivity or dip switch setting with power applied. Power supply Common/Neutral and Control Signal "-"wiring to a



common is prohibited. Terminals 4 and 6 need to be wired separately.



Isolation relays must be used in parallel connection of multiple actuators using a common control signal inputs. The relays should be




Isolation relays are required in parallel applications. The reason parallel applications need isolation relays is that the motor uses two sets of windings, one for each direction. When one is energized to turn the actuator in a specific direction a voltage is generated in the other due to the magnetic field created from the first. It's called back EMF. This is not an issue with one actuator because the voltage generated in the second winding isn't connected to anything so there is no flow. On parallel applications without isolation, this EMF voltage energizes the winding it is connected to on the other actuators in the system, the actuators are tying to turn in both directions at once. The EMF voltage is always less than the supply voltage due to the resistance of the windings, so while the actuator still turns in the commanded direction, the drag from the other reduces the torque output and causes overheating.



## WARNING! LIVE ELECTRICAL COMPONENTS!

During installation, testing, servicing and troubleshooting of this product, it may be necessary to work with live electrical components. Have a qualified licensed electrician or other individual who has been properly trained in handling live electrical components perform these tasks. Failure to follow all electrical safety precautions when exposed to live electrical components could result in death or serious injury.



Date created, 04/03/2020 - Subject to change. © Belimo Aircontrols (USA), Inc